



- Asbestos air sampling location
- Asbestos, TSP/metals sampling and ambient dust monitoring location
- Former site railroad (removed)
- STATUS**
- Debris remains, awaiting disposal
- Site boundary

- Building D**
- STATUS**
- Awaiting asbestos abatement
- Building demolished
- Decontamination in progress
- Demolition in progress

Basemap source: Esri

UNITED STATES
ENVIRONMENTAL PROTECTION AGENCY

EAGLE ZINC OPERABLE UNIT 1
MONTGOMERY COUNTY, HILLSBORO, ILLINOIS

DEMOLITION PROGRESS TRACKING
March 17 2015
BUILDING D DETAIL

EPA REGION 5 RAC 2 | REVISION 0 | March 2015

ST

SulTRAC

document path: C:\Users\ncentola\Projects\EagleZinc\demolition progress tracking\demolition progress tracking 38358989 v08 Building D.mxd author: ASchubert